



Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/50005DE8427/1

Work Order Type: Weatherization

Audit Name: Audit DE8427

CLIENT INFORMATION

Client Name:

Address:

Client ID: 50005DE8427

, TN 38023

Alt. Client ID:

AGENCY INFORMATION

Agency: 50005DE

Agency Phone: (901) 476-5226

Address: P. O. BOX 634, 915 HWY 51 SOUTH
COVINGTON, TN 38019

Fax: (901) 476-5258

Email Address: gloria.v.williams@tn.gov

Agency Contact: Treadwell, Dwight

Work Phone: (901) 274-8336

Cell Phone: (865) 335-4834

Email Address:

Company Name & License Number: _____

Contractor's Signature: _____

COMMENT

Roof at this structure is extremely leaky. Some rafters are rotted.

No attic insulation is recommended. Agency will investigate alternate source of funding to repair roof and add attic insulation

Certified Lead Renovator required

Client Name:

Client ID: 50005DE8427

Alt. Client ID:

Work Order (Bid Form)

Work Order Name: WO/50005DE8427/1

Report Run On: 5/27/2010

DOE Weatherization Assistant

Version 8.5.0

Page 1 of 7

Measures

Measure 1 Replace broken pane in Window #8				Components			Inspected					
Comment				<input type="text"/>								
				Estimated			Actual					
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total			
10	Unspecified	Misc Material	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>			
Other Detail												
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>			
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>			
Measure Sub Total:						<input type="text"/>	Sub Total:			<input type="text"/>		
Field Notes:												
<input type="text"/>												

Measure 2 Replace front door				Components			Inspected					
Comment Front door is in extremely bad disrepair - recommend replacing front door with standard door				<input type="text"/>								
				Estimated			Actual					
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total			
10	Unspecified	Misc Material	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>			
Other Detail												
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>			
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>			
Measure Sub Total:						<input type="text"/>	Sub Total:			<input type="text"/>		
Field Notes:												
<input type="text"/>												

Measure 3
Replace gable vent at back of house

Components

Inspected
☐

Comment

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Misc Material	Each	1					

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:

Sub Total:

Field Notes:

Measure 4 Infiltration Redctn**Components****Inspected****Comment** AIR INFILTRATION MEASURES:☐

1. Repair Hole in wall - Front Porch area- old heating system
2. Replace framing window 1,
3. Caulk all windows on the inside and outside for air sealing
4. Block and seal AC - Bedroom and Front Room w3 - w11
5. Glaze windows - W3, W4, W6, W7, W8, W9 - MUST REMOVE STORMS AND REPLACE WHEN DONE
8. Weatherstrip back door
9. Patch holes under kitchen sink
10. Air seal plumbing penetrations - Kitchen - Bathroom
11. Repair hole under washer
12. repair hole in kitchen ceiling
13. Patch hole in ceiling front bedrooms -
14. Repair holes in living room ceiling - sagging also
15. Air seal ceilings
17. Air Seal around Old Heating system register locations in each room

#	Material / Labor	Description / Comment	Units	Estimated		Actual			
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Miscellaneous Supplies	Infiltration Reduction	Each	1					
Other Detail									
Measure Sub Total:							Sub Total:		

Field Notes:

Client Name:

Client ID: 50005DE8427

Alt. Client ID:

Work Order (Bid Form)

Work Order Name: WO/50005DE8427/1

Report Run On: 5/27/2010

DOE Weatherization Assistant

Version 8.5.0

Page 4 of 7

Measure 5 DWH Pipe Insulation				Components				Inspected	
Comment									
				Estimated		Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1					
2	Labor	DHW Pipe Insulation	Each	1					
Other Detail									
Measure Sub Total:							Sub Total:		
Field Notes:									

Measure 6 Replace A/C				Components Window AC				Inspected	
Comment									
				Estimated		Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Cooling Equipment	Window A/C -	Each	1					
2	Labor	Window A/C -	Each	1					
Other Detail									
Measure Sub Total:							Sub Total:		
Field Notes:									

Measure 7 Attic Ins. R-38**Components** 1106 SF**Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Attic Insulation - Blown Cellulose - R-38	SqFt	1106	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Measure 8 Wall Insulation****Components** Back,East,Front,Wes
t**Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	932.7	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:**

Client Name:

Client ID: 50005DE8427

Alt. Client ID:

Work Order (Bid Form)

Work Order Name: WO/50005DE8427/1

Report Run On: 5/27/2010

DOE Weatherization Assistant

Version 8.5.0

Page 6 of 7

Measure 9 Replace Htg. System**Components** 50K BTU vented wall**Inspected****Comment** Replace unvented space heater with 50K BTU vented wall heater☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Heating Equipment	Space Heater - 35 kBtu/h NG Existing, 27 - 38 kBtu/h NG Post	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Space Heater - 35 kBtu/h NG Existing, 27 - 38 kBtu/h NG Post	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total: **Sub Total:** **Field Notes:****Measure 10 CO Monitor is Needed****Components****Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	CO monitor	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Hour	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total: **Sub Total:** **Field Notes:****Work Order Grand Total:** **Grand Total:**

Client Name:

Client ID: 50005DE8427

Alt. Client ID:

Work Order (Bid Form)

Work Order Name: WO/50005DE8427/1

Report Run On: 5/27/2010

DOE Weatherization Assistant

Version 8.5.0

Page 7 of 7